



Westrac Ltd Fenix Warranty Policy

Westrac warrants all Fenix flashlights and headlights for a period of twelve (12) months from date of purchase that the light is free of defects in material and workmanship under normal use.

Westrac undertakes in its sole discretion to repair or replace a returned light that after a forty-eight (48) hour analysis has been verified to have failed due to a defect in materials and/or workmanship under normal use. Return the light along with your original sales receipt or satisfactory proof of purchase to any Westrac Branch.

This limited warranty is valid for one (1) year. The warranty period begins on the date of purchase and expires twelve (12) months after the date printed on the sales receipt. Should the light fail, due to a defect in materials and/or workmanship, it will be replaced with the same model light, free of charge. If the same model light is not available, it will be replaced with a similar specification and quality light. Warranty will NOT apply to the replacement light.

Westrac holds the right to replace only part of the light if the defect is found to not be the whole light. If the light is validated to receive the warranty, only the defective part will be replaced as opposed to the entire unit, unless the entire unit is found to be defective. Westrac doesn't warrant normal wear of the light.

Battery leakage is not covered under the warranty. You are purchasing a high-quality flashlight so it is recommended that you select high-quality batteries to specifications for your light. All alkaline batteries will leak over a period of time. If you aren't going to use your flashlight for 3 weeks or more, it is recommended you remove alkaline batteries to minimize the chances of battery leakage.

Westrac does not warrant any Fenix accessories (such as pocket clips, lanyards, and holsters) to the same one (1) year warranty. Fenix batteries are only subject to receive 45 days warranty.

WARRANTY DOES NOT COVER DAMAGE TO THE LIGHT OR BATTERY CAUSED BY

 Misuse, abuse, moisture, overcharging due to not using recommended chargers or modification of original light.